

USB-Link™ 2 Drivers: Release Notes

Version 2.6.0.2 – Release Date: 05/31/2017

Features Added/Improved

- Firmware version 0.016019 is included in this release
- Updated firmware to fix issue with USB-Link 2 becoming unresponsive after sitting idle for 30 minutes
- Updated to return correct RP1210 error code on connect
- Updated firmware to support setting and filtering of up to 33 flow controls for ISO15765

Version 2.3.0.0 – Release Date: 07/18/2016

Features Added/Improved

- Added ISO15765 Single Wire Pin Select for J2534
- Added VPW 4x J2534 Support
- Improved RP1210 ioctl GetBusStats
- Improved Windows Bluetooth Connection Time

Bugs Fixed

- Fixed Command 3 is clearing all filters in an ISO15765 connection
- Fixed Update Installer to use .NET 4.6 (modified install to display warning if download fails)

Version 2.2.0.23 – Release Date: Not Released*

Features Added/Improved

- Move J1939 Transport Protocol Support to Firmware
- Update DMux32 Test app to show default and connected baud rate and channel

Bugs Fixed

- Users with Webroot Antivirus are experiencing Blue Screens with USBLink2 and INLINE7 installers
- Issue with ISO 15765 SendCommand Receiving ERR_INVALID_COMMAND

- USB-Link 2 Explorer link is not removed from programs menu after uninstalling drivers
- Communication over Wi-Fi is slow on a data bus with light traffic
- Programming with Wi-Fi is slow
- Update Installer to Use .NET Framework 4.6 (.NET 4.5 not supported on Windows 10)
- J1850 VPW bus goes blank after several seconds of high bus usage
- VCI connects to the first available open network
- Unable to change speed limit settings on the Hino VCS controller
- Unable to read DTC and Support Information on Hino VCS
- Device does not recover when it goes out of range connected via Bluetooth

**Features and Bug Fixes incorporated into the Version 2.3.0.0 release.*

Version 2.2.0.19 – Release Date: 04/18/2016

Features Added/Improved

- Improved Wi-Fi performance
- Improved ISO-15765 flow control and filters
- Improved Volvo Tech Tool connection time

Bugs Fixed

- Minor bug fixes

Version 2.1.0.12 – Release Date: 11/09/2015

Features Added / Improved

- Autobaud J1939-16 searching order
New order is 1M, 667K, 500K, 250K, 125K
Old order was 250K, 500K, 1M, 667K, 125K

Bugs Fixed

- Corrected Reprogramming MBE engines disconnects from PLD (KW2000)
- Fixed Auto baud support for CAN Channel 3
- Enabled Bluetooth discovery by default
- Fixed issue with Jungo driver install
- Fixed KWP2000 fast init failed when explorer is open
- Fixed intermittent autobaud crash

Version 2.0.1.9 – Release Date 09/11/2015

New Features / Enhancements

- Added support for Wi-Fi connectivity

Firmware Version

- 0.012148